

AINOS THEOS

THE BUILDING SOLUTION PEOPLE

HOLIDAY VILLA HOTEL SUBANG - NEW CANOPY INSTALLATION AT VICTORIAN BALLROOM GARDEN SITE & SIDE WALK AREA EXISTING SITE CONDITION



Photo 1
Front entrance at Holiday Villa Hotel & Resorts Subang View



Photo 2
Victoria N Ballroom polycarbonate skylight defective view



Photo 3
General view of Garden Dome Site of defective polycarbonate skylight



Photo 4
Side view of defective polycarbonate skylight view



Photo 5
cracked / defective polycarbonate skylight view at garden dome area



Photo 9
Garden Dome site cracked polycarbonate view



Photo 7
Another view of garden dome site defective polycarbonate skylight view



Photo 8
Top view of defective polycarbonate skylight at garden dome site



Photo 6
Another view of defective polycarbonate skylight view

RIGHT WAY INDUSTRIAL (MALAYSIA) SDN BHD – DEFECTIVE METAL ROOF AT BLOCK G & H, R.C. ROOF AT BLOCK A EXISTING SITE CONDITION



PHOTO 1
Ceiling water stained from metal roof leakage view



PHOTO 2
Water stained From above metal roof defective view



PHOTO 3
Another view of ceiling water stained from metal roof leakage



PHOTO 4
Below view of ceiling water stained from metal roof leakage



PHOTO 5
Top view of defective metal roofing



PHOTO 6
Another view of defective metal roof



PHOTO 7
Ceiling water stained from metal roof leakage view




PHOTO 8
Water stained from above metal roof defective view



PHOTO 9
Side view defective metal roof

KELAB TAMAN PERDANA DIRAJA KUALA LUMPUR- INSTALLATION OF NEW WATER TANK EXISTING SITE CONDITION



Photo 1
Front elevation of water tank view



Photo 2
Corroded exterior water tank view



Photo 3
Side elevation of water tank view



Photo 4
Another view of existing corroded and leakage water tank view



Photo 5
Smaller water tank view



Photo 6
Another view of smaller water tank corroded view

KELAB TAMAN PERDANA DIRAJA KUALA LUMPUR- CAR PARK BASEMENT B2 C.I. PIPING SYSTEM EXISTING SITE CONDITION



Photo 1
Car park basement B2 m/s c. l. pipes leakage



Photo 2
Existing elbow shape leakage / defective at double front fitting view



Photo 3
Side view of c.l. piping leakage at car park B2 area



Photo 4
Another view of existing leakage c.l. pipes view at car park B2 area.



Photo 5
Another view of existing leakage c.l. pipes view at car park B2 area.



Photo 6
Front view of leakage piping

AINOS THEOS

THE BUILDING SOLUTION PEOPLE

Shatter Proof Glass System



AINOS THEOS

THE BUILDING SOLUTION PEOPLE

Retractable Awning System Past Project Reference



Damansara Perdana



Sri Sempurna School, Cheras