


Basement

14 Phoenix Avenue Bungalow





2. Application of 1st coat waterproofing membrane.





3. Completion of waterproofing membrane.



4. Installation of protection board prior backfilling.

AINOS THEOS SDN. BHD.(867821-M)



HOLIDAY VILLA HOTEL SUBANG - NEW CANOPY INSTALLATION AT VICTORIAN BALLROOM GARDEN SITE & SIDE WALK AREA

EXISTING SITE CONDITION







Photo 1 Front entrance at Holiday Villa Hotel & Resorts Subang View

Photo 2 Victoria N Ballroom polycarbonate skylight defective view

Photo 3 General view of Garden Dome Site of defective polycarbonate skylight



Photo 4 Side view of defective polycarbonate skylight view



Photo 5 cracked / defective polycarbonate skylight view at garden dome area



Photo 9 Garden Dome site cracked polycarbonate view



Photo 7 Another view of garden dome site defective polycarbonate skylight view



Photo 8 Top view of defective polycarbonate skylight at garden dome site



Photo 6 Another view of defective polycarbonate skylight view

AINOS THEOS SDN. BHD.(867821-M)



ABSEILING CLEANING SYSTEM FOR COMMERCIAL, HYPERMARKET HOTEL INDUSTRIES.



Photo 1 Hotel Glass Window Cleaning System



Photo 3 Hotel Cleaning System in progress....



Photo 5 Commercial Abseiling cleaning system in progress...



Photo 7 Hypermarket exterior abseiling cleaning system in progress...



Photo 2

Another view of Hotel Abseiling cleaning system in progress....



Photo 4 Commercial / Office complex Abseiling Cleaning System in progress...



Photo 6 Glass and arocarbon abseiling cleaning system in progress...



Photo 8 Hypermarket exterior window and panel cleaning system

AINOS THEOS SDN. BHD.(867821-M)

AINOS THEOS THE BUILDING SOLUTION PEOPLE

RIGHT WAY INDUSTRIAL (MALAYSIA) SDN BHD – DEFECTIVE METAL ROOF AT BLOCK G & H, R.C. ROOF AT BLOCK A EXISTING SITE CONDITION



PHOTO 1 Ceiling water stained from metal roof leakage view



Water stained From above metal roof defective view



PHOTO 3 Another view of ceiling water stained from metal roof leakage



PHOTO 4 Below view of ceiling water stained from metal roof leakage



PHOTO 5 Top view of defective metal roofing



PHOTO 6 Another view of defective metal roof



PHOTO 7 Ceiling water stained from metal roof leakage view



PHOTO 8 Water stained from above metal roof defective view



PHOTO 9 Side view defective metal roof

AINOS THEOS SDN. BHD.(867821-M)

AINOS THEOS THE BUILDING SOLUTION PEOPLE

KELAB TAMAN PERDANA DIRAJA KUALA LUMPUR- INSTALLATION OF NEW WATER TANK EXISTING SITE CONDITION



Photo 1 Front elevation of water tank view



Photo 3 Side elevation of water tank view



Photo 5 Smaller water tank view




Photo 2 Corroded exterior water tank view



Another view of existing corroded and leakage water tank view



Photo 6 Another view of smaller water tank corroded view

AINOS THEOS SDN. BHD.(867821-M)



KELAB TAMAN PERDANA DIRAJA KUALA LUMPUR- CAR PARK BASEMENT B2 C.I. PIPING SYSTEM EXISTING SITE CONDITION



Photo 1 Car park basement B2 m/s c. I. pipes leakage



Photo 2 Existing elbow shape leakage / defective at double front fitting view



Photo 3 Side view of c.l. piping leakage at car park B2 area



Photo 4 Another view of existing leakage c.l. pipes view at car park B2 area.





Photo 5 Another view of existing leakage c.l. pipes view at car park B2 area.



Photo 6 Front view of leakage piping

AINOS THEOS SDN. BHD.(867821-M)





AINOS THEOS SDN. BHD.(867821-M)



Retractable Awning System Past Project Reference



Sri Sempurna School, Cheras

AINOS THEOS SDN. BHD.(867821-M)