



KELAB TAMAN PERDANA DIRAJA KUALA LUMPUR - MULTI PURPOSE HALL - BADMINTON COURT FLOORING TO VARNISH EXISTING SITE CONDITION



Photo 1 Kelab Taman Perdana Diraja Kuala Lumpur Multi Purpose Hall view



Photo 2
Badminton Court flooring view



Photo 3 Existing badminton flooring general view



Photo 4
Front view of multi purpose hall flooring view



Photo 5 Skirting flooring view



Photo 6 Another view of existing flooring view



Photo 7
Existing flooring proposed for varnish and maintenance view



Photo 8
Another view of existing flooring view



Photo 9 Existing flooring view




Photo 10 Existing flooring view



Photo 11 Flooring view near courter area



Photo 12 Gneral view of badminton view

AINOS THEOS THE BUILDING SOLUTION PEOPLE

HOLIDAY INN KUALA LUMPUR GLENMARIE - KITES RESTAURANT FLOOR DECK AREA EXISTING SITE CONDITION




Photo 1
Front View of Kites Restaurant exterior defective floor deck



Photo 2 Kites Restaurant view



Photo 3
Kites Restaurant defective flooring deck view



Photo 4
Another view of defective flooring deck



Photo 5 Another view of Kites Restaurant flooring deck




Photo 6
Side view of floor decking at Kites Restaurant



KELAB TAMAN PERDANA DIRAJA KUALA LUMPUR- VARNISH COATING SURFACE AT BANQUET HALL **EXISTING SITE CONDITION**







Photo 1 Photo2 Front entrance at Kelab Taman Perdana Diraja K.Lumpur Banquet Hall

Photo 3 Banquet Hall wooden flooring defective view





Photo 4 Another view of defective flooring at Banquet Hall

Photo 5 Defective flooring required varnish at Banquet Hall





Photo 6 Debond wooden flooring at Banquest Hall view

Photo 7 General view of Banquet Hall wooden flooring





Varnish cooating EKASEAL 32 matt Waterbase Polyurethane timber floor finish material, Made in USA equivalent quality to varnish BANQUET HALL FLOOR AREA.