

ROYAL LAKE CLUB- POOLSIDE BAR AREA TO UPGRADE WITH STAINLESS STEEL & TEMPERED GLASS RAILING SYSTEM EXISTING SITE CONDITION - WORK-IN-PROGRESS







Date 31/8/2010

Photo 3 Site mobilization and hacking work commence at poolside bar area view..

Site mobilization haulding work in progress at poolside bar area...



One side of poolside bar area hacking at planter box in progress.

Photo 5 Completion and painting at round wall area view





Photo 8 Completion of tempered glass at poolside bar area view



Photo 9 Another view of tempered glass completion at stain steel railing area.