

PAINTING SYSTEM AT ANGKUPURI CONDO. MONT KINARA
Wall washing of high pressure water jacket of Work-in-progress . 22/07/2014



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

PAINTING SYSTEM AT ANGKUPURI CONDO. MONT KINARA
Wall washing of high pressure water jacket of Work-in-progress . 22/07/2014



Photo 1




Photo 2



Photo 3



Photo 1



Photo 2



Photo 3




Photo 4




Photo 5



Photo 6



Photo 1



Photo 2




Photo 3

PAINTING SYSTEM AT ANGKUPURI CONDO. MONT KINARA
Wall washing of high pressure water jacket of Work-in-progress . 22/07/2014



Photo 1



Photo 2



Photo 3




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6




Photo 1



Photo 2



Photo 3

PAINTING SYSTEM AT ANGKUPURI CONDO. MONT KINARA
Wall crack repair of Work-in-progress . 22/07/2014



Photo 1



Photo 2



Photo 3




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 1



Photo 2



Photo 3

PAINTING SYSTEM AT ANGKUPURI CONDO. MONT KINARA
Wall undercoat for oil based paint of Work-in-progress . 12/08/2014



Photo 1



Photo 2



Photo 3



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 1



Photo 2



Photo 3