

PROPOSED ROOF TOP SKYLITE REPLACEMENT TO ZINC. PLATE @ TECSO KAJANG  
23/10/2017



Photo 1



Photo 2



Photo 3



Photo 4

**AINOS THEOS**  
SAFETY TOOL BOX BRIEFING

TITLE: *Tecso Kajang skylite*  
DATE: *23/10/17* TIME: \_\_\_\_\_  
VENUE: \_\_\_\_\_

ATTENDANCE LIST			
NO	NAME	COMPANY	SIGNATURE
	CHANDRAN LATIH		<i>[Signature]</i>
	SHARIF		<i>[Signature]</i>
	MHAZRUL ISLAM		<i>[Signature]</i>
	(BILAL)		<i>[Signature]</i>

REMARKS/ MATTERS TO DISCUSS:

- 1- PPE Safety check-
- 2- Job scope/work elevation-
- 3- Worker's health condition- fit to work check
- 4- Equipment/ material briefing
- 5- Others

Photo 5



Photo 6



Photo 7



Photo 8



Photo 10




Photo 11



Photo 12



Photo 13



Photo 14



PROPOSED ROOF TOP SKYLITE REPLACEMENT TO ZINC. PLATE @ TECSO KAJANG  
23/10/2017



Photo 1

**AINOS THEOS**  
THE BUILDING SOLUTION PEOPLE

**SAFETY TOOLBOX BRIEFING**

TITLE: Tecso Kajang skylite  
DATE: 23/10/17  
VENUE: Tecso Kajang

ATTENDANCE LIST

NO	NAME	COMPANY	SIGNATURE
1	MPINZROL ISLAM		[Signature]
2	CHANDRAA		[Signature]
3	SHILDAI		[Signature]
4	LATIF		[Signature]
5	SHARIF		[Signature]

REMARKS/ MATTERS TO DISCUSS:

1. PPE Safety check
2. Job scope/work elevation
3. Worker's health condition- fit to work check
4. Equipment/ material briefing
5. Others

Photo 2



Photo 3



Photo 4




Photo 5



Photo 6




Photo 7




Photo 8




Photo 9



Photo 10



Photo 11



Photo 12