

**SIN CHEW DAILY, PETALING JAYA - ADMIN BLOCK -REPAINTNG & WATERPROOFING SYSTEM**  
**WORK - IN - PROGRESS....**



Photo 1  
Front view of Sin Chew Daily, Jln. Petaling, Kuala Lumpur.



Photo 3  
Another side elevation view exterior wall repainting and waterproofing until the staircase area



Photo 4  
Another view of high humidity or dampness causing mildew/algae/fungi growth near toilet area...



Photo 5  
Staircase area view




Photo 6  
Defective plaster wall at side elevation near toilet area



Photo 7  
Side elevation defective wall view



Photo 8  
Defective plaster wall near toilet and staircase area view



Photo 9  
Defective plaster wall view

