



Photo 1
Bank Negara Malaysia Resorts Kuala Terengganu front entrance view




Photo 2
BNM Resorts Bungalow front entrance completed composite Railing view



Photo 3
BNM Resort Bungalow next to caretaker's unit composite railing view




Photo 4
Side entrance of bungalow unit staircase area of duly completed railing view



Photo 5
Bungalow unit Rear elevation of duly completed Composite Railing view



Photo 6
Another rear elevation of bungalow unit composite Railing duly completed view



Photo 7
Another view of bungalow Gazebo Composite Railing



Photo 8
Bungalow Gazebo Composite Railing duly completed view



Photo 9
Chalet A rear elevation Composite Railing completed view



Photo 10
Chalet A, duly completed Composite Railing at Staircase and Rear Elevation view



Photo 11
Chalet B Composite Staircase and Railing duly completed view



Photo 12
Chalet C Composite Railing and Staircase duly completed view