

TOTAL EXTERIOR FACADE IRON DITCH COVER REPLACEMENT & PAINTING SYSTEM

Ditch cover of iron replacement and painting in progress at Tunas Kijang of Bank negara, 10/04/2012



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9