

Water Leaking at AEON BiG KOTA DAMANSARA , 09/05/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12

Water Leaking at AEON BiG KOTA DAMANSARA , 09/05/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6




Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12

Water Leaking at AEON BiG KOTA DAMANSARA , 09/05/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12

Water Leaking at AEON BIG KOTA DAMANSARA
Water proofing System at Metal Roof work- in progress, 11/11/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5




Photo 6




Photo 7



Photo 8



Photo 9



Photo 10



Photo 11




Photo 12

Water Leaking at AEON BiG KOTA DAMANSARA

Water proofing System at Metal Roof work- in progress, 11/11/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10




Photo 11



Photo 12

Water Leaking at AEON BiG KOTA DAMANSARA
Water proofing System at Metal Roof work- in progress, 03/12/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9




Photo 10



Photo 11



Photo 12