

WATER LEAKING AT AEON BIG HIGHPERMARKET OF WANGSA MAJU  
Water Leaking at RC gutter and steel gutter of Sales Area . 08/01/2014



Photo 1



Photo 2 sales area staff entrance



Photo 3



Photo 4 R C gutter



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10 store room area



Photo 11



Photo 12 steel gutter

**WATER LEAKING AT AEON BIG HIGHPERMARKET OF WANGSA MAJU**  
Water Leaking at RC gutter and steel gutter of Sales Area . 08/01/2014



Photo 1



Photo 2




Photo 3




Photo 4 sales area



Photo 5 3 C counter



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12

WATER LEAKING AT AEON BIG HIGHPERMARKET OF WANGSA MAJU  
PARTY WALL / RC SLAB INTERSETION REPAIR FOR AEON BIG WANGSA MAJU, 04/06/2013



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12

**WATER LEAKING AT AEON BIG HIGHPERMARKET OF WANGSA MAJU  
PARTY WALL / RC SLAB INTERSETION REPAIR FOR AEON BIG WANGSA MAJU, 04/06/2013**



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12