

PROPOSED WATER-PROOFING WORKS FOR TESCO @ TESCO AMPANG  
WORK-IN PROGRESS



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6




Photo 7



Photo 8



Photo 9 Site cleaning



Photo 10 After cleaning



Photo 11



Photo 12 Crack repair



# PROPOSED WATER-PROOFING WORKS FOR TESCO @ TECO AMPANG WORK-IN PROGRESS



Photo 1 Angle fillet at all corner



Photo 2 Coring work



Photo 3



Photo 4 Coring 6"- install downpipe



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



# PROPOSED WATER-PROOFING WORKS TO TESCO @ TESCO AMPANG WORK-IN PROGRESS



Photo 1 Wip View



Photo 2




Photo 3 Apply primer bitumen at roof



Photo 4 Wip View



Photo 5 Cleaning before apply primer



Photo 6 Applying of primer



Photo 7



Photo 8 Primer application view



Photo 9 Primer curing



Photo 10 Wip View



Photo 11



Photo 12 Torch-on membrane



# PROPOSED WATER-PROOFING WORKS TO TESCO @ TESCO AMPANG WORK-IN-PROGRESS



Photo 1 outlet installation



Photo 2



Photo 3 Touch up of bitumen primer



Photo 4



Photo 5 Torch on membrane work



Photo 6



Photo 7 Wip View



Photo 8



Photo 9 Wip View



Photo 10 membrane work



Photo 11



Photo 12 Wip View