

### PROPOSED REPLACEMENT GUTTER AT UPPER TIER OF PLAYLAND @ TECSO KAJANG 28/11/2017




Photo 11

Photo 12



### PROPOSED REPLACEMENT GUTTER AT UPPER TIER OF PLAYLAND @ TECSO KAJANG 28/11/2017






Photo 2



Photo 3

Photo 9



Photo 4



Photo 5




Photo 8






Photo 7







#### PROPOSED REPLACEMENT GUTTER AT UPPER TIER OF PLAYLAND @ TECSO KAJANG 28/11/2017





# PROPOSED REPLACEMENT GUTTER AT UPPER TIER OF TESCO SALES AREA @ TECSO KAJANG 28/11/2017




Photo 10


Photo 11



### PROPOSED REPLACEMENT GUTTER AT UPPER TIER OF TESCO SALES AREA @ TECSO KAJANG 5/12/2017












Photo 7




Photo 10



Photo 8





Photo 12



# PROPOSED REPLACEMENT GUTTER AT UPPER TIER OF TESCO SALES AREA @ TECSO KAJANG 5/12/2017

5/12/2017		
<image/> <section-header><section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header>	Photo 2	Photo 3
Photo 4	Photo 5	Photo 6
		Bhat 3
Photo 7	Photo 8	Photo 9

Photo 10

Photo 11